

# PRODUCT CHANGE NOTIFICATION (PCN)

Product Category AUDIO VISUAL 20210215-1

Product Group ROAR

ISSUE DATE: 20210215

IMPACTED REGIONS:  NA  EMEA  LATAM  AP

REASON FOR CHANGE:  DISCONTINUATION  
 OTHER

**DESCRIPTION OF CHANGE: (Required)**

The following parts are discontinued with certain parts having a replacement through our Atlona offering.

- Compatible HDMI patch cables are offered through Atlona through the LinkConnect Line
- Replacement HDBaseT Extenders are offered through Atlona's Avance Line

**IMPACTED PART NUMBERS AND REPLACEMENT PART NUMBERS: (where applicable)**

[Reference Page 2 / Linked PDF](#)

**DATES: DISCONTINUATION AND NEW PRODUCT AVAILABILITY:**

SCHEDULE FOR CHANGE	Year (YYYY)	Month (MM)	Day (DD)
New product sample availability date	2021	2	16
Old product discontinuation date*	2021	2	22

**\*Important:** A return material authorization (RMA) may be obtained for these affected part numbers and they may be returned up to 60 days after the product discontinuation announcement date if purchased within the last 18 months and subject to the return policy requirements outlined in Panduit's Authorized Distributor Policy. Please contact your local Panduit Customer Experience team if you have any questions.

<b>Impacted Part Numbers</b>	<b>Compatibility Type</b>	<b>Replacement Part 1</b>
CMBBCMR	No Replacement	NO-REPLACEMENT
CMBBLWH	No Replacement	NO-REPLACEMENT
CMBBRKT	No Replacement	NO-REPLACEMENT
CMBBSWH	No Replacement	NO-REPLACEMENT
CMHDBTBRX	No Replacement	NO-REPLACEMENT
CMHDBTBTX	No Replacement	NO-REPLACEMENT
CMHDBTWPTX	No Replacement	NO-REPLACEMENT
CMHDBTWRX	No Replacement	NO-REPLACEMENT
HDMI1MBL	No Replacement	NO-REPLACEMENT
HDMI1MWH	No Replacement	NO-REPLACEMENT
HDMI2MBL	No Replacement	NO-REPLACEMENT
HDMI2MWH	No Replacement	NO-REPLACEMENT
HDMI4MBL	No Replacement	NO-REPLACEMENT
HDMI4MWH	No Replacement	NO-REPLACEMENT
HDMIA10M	No Replacement	NO-REPLACEMENT
HDMIA15M	No Replacement	NO-REPLACEMENT
HDMIA20M	No Replacement	NO-REPLACEMENT
HDMIA30M	No Replacement	NO-REPLACEMENT
HDMIA50M	No Replacement	NO-REPLACEMENT
HDMIA75M	No Replacement	NO-REPLACEMENT
PND100	No Replacement	NO-REPLACEMENT
PND110	No Replacement	NO-REPLACEMENT
PND400	No Replacement	NO-REPLACEMENT
NK35MSCAW	Compatible	NK35MSCIW
NK35MSSAW	Compatible	NK35MSSIW
NKBNCMAWY	Compatible	NKBNCMIWY
NKFAW	Compatible	NKFIW
NKBPRAWY	No Replacement	NO-REPLACEMENT
NKBPBAWY	No Replacement	NO-REPLACEMENT
NKRTMRAW	No Replacement	NO-REPLACEMENT
NKRTMWAW	No Replacement	NO-REPLACEMENT
NKRTMYAW	No Replacement	NO-REPLACEMENT