







**Standardized Information Note (IN)**

1. Information Note basic data	
1.1 Company	 Micronas GmbH, Hans-Bunte-Straße 19, D-79108 Freiburg, Germany
1.2 Information Note No.	15010
1.3 Title of IN	Additional Marking Bottom Side for HAL 182x in Package TO92UA-2
1.4 Issue date	2015/07/07

2. Contact		
2.1 Contact supplier		
2.1.1 Name	Please contact your distributor.	
2.1.2 Phone		
2.1.3 Email		
2.2 Team supplier (optional)		
2.2.1 Name (optional)	2.2.2 Phone (optional)	2.2.3 Email (optional)

3. Description		
	Old	New
Description #1	Top side marking example: 	Top side marking example:  NO CHANGE!
Description #2	Bottom side marking: 	Bottom side marking:  OR 
Description #3		
Description #4		
Description #5		

4. Reason / motivation	
4.1 Motivation	A new tool in assembly enables cavity marking at the bottom side of our UA-Package. The top side marking and also the package drawing remain unchanged. No change in material, form, fit and function of the package. Mixed deliveries with and without bottom marking might be possible.
4.2 Additional explanation (optional)	

5. Marking of parts / traceability	
5.1 Description	No change in top side marking / Traceability available via lotnumber.

6. Timing / schedule		
6.1 Intended start of delivery	2016/04/01	Sample availability: January 29th, 2016

7. Attachments (e.g. additional documentation, pictures, part list....)

--

8. Affected parts									
8.1 Current						8.2 New (if applicable)			
8.1.1 Customer Part No.	8.1.2 Supplier Part Name	8.1.3 Supplier Part No. (optional)	8.1.4 Package Name	8.1.5 Part Description (optional)	8.1.6 Additional Part Information (optional)	8.2.2 Supplier Part Name	8.2.3 Supplier Part No. (optional)	8.2.4 Package Name	8.2.6 Additional Part Information (optional)
	HAL1821		PTO92UA-2						
	HAL1822		PTO92UA-2						
	HAL1823		PTO92UA-2						
	HAL1827		PTO92UA-2						
	HAL1829		PTO92UA-2						
