

**PCN1056
End-of-Life Notification
M-986-2R2P**

August 17, 2017

To Our Valued Customers:

As part of our ongoing product lifecycle management process, IXYS Integrated Circuits Division has transitioned the following products to an “End-of-Life” status. This decision was based on the review of historical unit shipments and product revenue performance.

The products identified for inclusion into our End-of-Life program are the following Multifunction (MF) Transceivers:

- M-986-2R2P MF Transceiver, 40-pin plastic DIP, Dual Channel
- M-986-2R2PL MF Transceiver, 44-pin PLCC, Dual Channel

There will be no Last Time Buy program for these devices. For additional design support, please contact applications engineering:

Applications Engineering Department
IXYS Integrated Circuits Division
78 Cherry Hill Dr.
Beverly, MA 01915
Phone: 978-524-6700

Sincerely,

Steven Andrezyk
Director of Marketing

Part Change Notification

The PCN number assigned to this change is **PCN1056** and should be referenced in any correspondence related to the change.

Products Affected

M-986-2R2P, M-986-2R2PL

Detailed Description of Change

IXYS Integrated Circuits Division has transitioned the M-986-2R2P and M-986-2R2PL devices to an End-of-Life status.

Reason for the Change

The End-of-Life decision is based on historical unit shipments and product revenue performance.

Anticipated Impact on Quality and Reliability

Not applicable.

Contact Information

For any questions related to the PCN notice, please contact IXYS Integrated Circuits Division's Quality Assurance Department as indicated below:

Martha Brandt
Quality Assurance Department
IXYS Integrated Circuits Division
78 Cherry Hill Dr.
Beverly MA, 01915
Phone: 978-524-6700

