

HellermannTyton

10/27/2020

Subject: Change Notification

To our valued Customer:

HellermannTyton continually evaluates our manufacturing and supply chain to provide you with quality service at a reasonable price. To better serve your business, we inform you of the following change in:

| Type (Only Checked Changes Apply) | | |
|---|--|--|
| <input checked="" type="checkbox"/> Production/assembly location | <input type="checkbox"/> Material | <input type="checkbox"/> End of Life w/ replacement |
| <input type="checkbox"/> Part Number/Ordering Code | <input type="checkbox"/> Packaging | <input type="checkbox"/> End of Life w/o replacement |
| <input checked="" type="checkbox"/> Country of Origin | <input type="checkbox"/> Point of Purchase | <input type="checkbox"/> Additional tool/refurbishment |
| <input type="checkbox"/> Design (fit, form, function) | <input type="checkbox"/> Point of Pick up | <input type="checkbox"/> Cost/Lead Time |
| <input type="checkbox"/> Engineering record (non-fit, form, function) | <input type="checkbox"/> Supply Chain | <input type="checkbox"/> Process |
| Additional Information | | |
| From: Production in Milwaukee, WI, USA | | To: Production in Escobedo, Nuevo Leon, MX |
| Scope | | |
| HT PN / Ordering Code | Customer PN | Change Effective* |
| 111-01564, 117-00019, 126-00045 | 111-01564, 117-00019, 126-00045 | 12/01/2020 |

*Effective date is subject to change based on availability

We ask that you please acknowledge this notification by 11/10/2020, informing us if a new PPAP is required. If we do not receive a response, we assume the change can be executed as planned without further notice. For additional information or assistance please contact your HellermannTyton Customer Service Representative. We appreciate your support in this change.

Thank you for your business,

Dylan Goetzke
Quality Project Administrator
Office: 414 355 1130 x 8751
Email: Dylan.goetzke@htamericas.com