




Product Change Notification (PCN)

PCN Number	508223	Date Issued	May 19, 2020
Reason for Change	Change to Product		
Change Type Description	This letter is to inform you that changes are being made to the part(s) identified in this Notice. The change may affect the fit, form, function or appearance of the parts, or it may result in a change to the specification. The pictures below show an example of the possible differences.		
Assessment of Change	Product will be fully qualified before it is shipped. Qualification reports will be available after below listed date		
Internal Molex Qualification Date	February 03, 2020		
Sample Availability Date (Changed Part)	February 03, 2020		
Planned Implementation Date	November 19, 2020		
Method of Identifying Change	Date code		

RELEASED

Before Change

- Micro USB 105133 series HSG Cover design change to improve the cap retention force and offset risk.
- Cover sides fork lock expand to 0.68mm, length 2.90mm



After Change

- Overview**
- 1. Change reason: increase the cover retention force for internal continuous improvement
 - 2. Product Impact
 - No impact to fit, form and function
 - 3. Part Number Impact
 - see attached part list
 - 4. Qualification Reports and samples available upon request after the running change date



Product Change Notification (PCN)

You may address any technical inquiries regarding this PCN by sending E-mail to pcn_coordinator@molex.com or your Local Sales Engineer.

Note: While responding, please retain "**PCN Notification:508223**" in the e-mail Subject line for faster response.

RELEASED

Molex, LLC
2222 Wellington Court
Lisle, IL 60532
TEL: 630-969-4747
www.molex.com

Molex Part #

1051330001

1051330001

1051330002

1051330011

1051330021

Part numbers affected:

105133-0001

105133-0011