



Product Change Notification

PCN#: POWER CONNECTORS, GROUNDING AND STEEL Issue Date: 20 Feb 2018

Impacted Regions: NA EMEA LATAM AP

Reason for Change: Discontinuation Other - Part Component Change

DESCRIPTION OF CHANGE:

Panduit will be changing the design of our hardware for all UGB series parts. The screw head will be reverting back to the original hex head design (hex and slotted) from the current Filister head (round and slotted). This improvement will make installations easier and faster for our customers. We hope to meet all customer expectations during this transition, and we urge you to contact product management with any comments or questions you may have.

PHOTOS/DRAWING



IMPACTED PART NUMBERS AND REPLACEMENT PART NUMBERS:

Please see list on next page



DATES: DISCONTINUATION AND NEW PRODUCT AVAILABILITY:

Schedule for Change	Year (YYYY)	Month (MM)	Day (DD)
New product sample availability date	2018	03	02
Old product discontinuation date*	2018	03	02

***Important:** After old product discontinuation date, the affected part numbers listed above will continue to be available for sale as long as supplies last. Product may be returned up to 60 days after the product discontinuation date.

CUSTOMER SERVICE CONTACTS:

ASIA PACIFIC	AUSTRALIA: 1-800 7263848 AUS-CustomerService@panduit.com	CHINA: 800-820-1900 CHN-CustomerService@panduit.com	HONG KONG: 800-965768 CHN-CustomerService@panduit.com	
	INDIA: 000 800 6501844 (Fixed Line) 000 800 6500369 (Mobile) IND-customer_service@panduit.com	INDONESIA: 001 803 65 7571 SGP-customer_service@panduit.com	JAPAN: +81-3-6863-6000 JPN-CS@panduit.com	
	KOREA: 02-2182-7300 KOR-CustomerService@panduit.com	MALAYSIA: 1800 801435 SGP-customer_service@panduit.com	SINGAPORE: 1-800-7263848 SGP-CUSTOMER_SERVICE@panduit.com	
	TAIWAN: 0080 165 1487 SGP-CUSTOMER_SERVICE@panduit.com	THAILAND: 001-800-65-6385 SGP-customer_service@panduit.com		
LATIN AMERICA	BRAZIL: 08000562613 (Toll Free) BRA-custservice@panduit.com	MEXICO: +52-33-37776000, X80520 01 800 360 86 00 (Toll Free) mex-customerservice@panduit.com	OTHER LA COUNTRIES: Phone USA 1-708-532-1800 TP-CS-INTERNATIONAL@panduit.com	
NORTH AMERICA	USA & CANADA: 1-800-777-3300 cs@panduit.com	EMEA	Phone:: +44 208 6017219 EMEA-CustomerServices@panduit.com	

To add a contact or to unsubscribe, please send an e-mail to PCN@panduit.com

IMPACTED PART NUMBER(s)	REPLACEMENT PART NUMBER(s)
UGB2/0-414-6	
UGB2/0-414-12	
UGB2/0-414-18	