

Amphenol Canada Corp - Product Change Notice (PCN)

PCN Date	Feb 25 2019
Supplier Name:	Amphenol Canada Corp
Amphenol Canada PCN Number	PCN-C1392
Description of Change	To change connector contact area plating type from brush Au to selected plating Au.
Reason for Change	To improve the plating efficiency.
Summary of changes between new and old part	No change on appearance
Traceability guidelines (lot code / date code, markings, ship date...)	N/A
Last Time Buy Date	N/A
Datasheet attached? & Filename(s)	N/A
Qual Test data attached? & Filename(s)	N/A

Customer Part Number	Amphenol Old Part Number	Amphenol New Part Number	PCN Effectivity Date	Samples Availability Date	Last Time Buy Date	Expected Supplier Qual Date
N/A	FS1Z3820Z610	Keep the same PN	28-Feb-19	15-Mar-19	N/A	N/A
N/A	FS1Z3820Z620	Keep the same PN	28-Feb-19	15-Mar-19	N/A	N/A
N/A	FS1Z3820Z640	Keep the same PN	28-Feb-19	15-Mar-19	N/A	N/A
N/A	FS1Z3820Z641	Keep the same PN	28-Feb-19	15-Mar-19	N/A	N/A
N/A	FS1Z3820Z650	Keep the same PN	28-Feb-19	15-Mar-19	N/A	N/A
N/A	FS1Z3820Z660	Keep the same PN	28-Feb-19	15-Mar-19	N/A	N/A
N/A	FS1Z3820Z670	Keep the same PN	28-Feb-19	15-Mar-19	N/A	N/A