

## **Product Obsolescence Notification**

PCN # 10451506

To: All active customers

From: Paul Ee

CC:

Date March 12, 2010

Economic pressures are requiring that Molex prune some of our underperforming products. Molex recognizes that this is an inconvenience for our customers so we will continue to accept additional orders for these products through November 15, 2010 to allow you sufficient time to transition to an alternate product.

Part Numbers Affected: See attached file

Last Order Entry Date: Nov. 15, 2010

Last Ship Date: Dec. 31, 2010

For further information please contact your local sales representative.

## **PCN** Obsolescence special note:

If no last time buy orders are received by Molex within 180 days after issue date of the Obsolescence PCN, Molex reserves the right to terminate production at any time at it's own discretion. MOQ and lead time will be negotiated at time of order placement and will be dependent upon material availability. Molex will make all efforts to meet customer order requirements. Orders placed after Obsolescence Notification and subsequently cancelled will be subject to a cancellation charge.

Molex, Inc.

2222 Wellington Court Lisle, Il 60532 TEL: 630-969-4747

www.molex.com

Material	Material Description	Replacement Part Number
0717360006 0717360011 0717360013 0738185101 0781220062 0872210021 0872210026 0876301001 0876301003 0876301011	05 DIMM Skt MK Forklock Pd-Ni 168Ckt .050 DIMM Multi-Key Nylon Assy 208Ckt 1mm FB Dimm 28.5deg O/Lub .76AuLF 240Ckt SCSI/2mm/PWComboStrdMt.76AuLF 68+12+4Ckt SCSI/2mm/PWComboStrdMt.76AuLF 68+12+4Ckt 1.27mm MK DIMM Assy .38AuLF 100Ckt 1.27mm MK DIMM Assy .38AuLF 100Ckt 1.27mm MK DIMM Assy .38AuLF 100Ckt	