

1 Products affected

Product hierarchy no. *				Part no.	SBU	Type / Description	Customer part no.
SBU	PG	PUG	Type				
01	002	010	0000000513	0031.3501	Circuit Protection	FAS fuse holder	n/a
				0031.3502		FAS fuse holder socket	n/a
				0031.3511		FAS fuse holder	n/a
				0031.3512		FAS fuse holder socket	n/a
				0031.3521		FAS fuse holder	n/a



*SBU (2-digit) / PG (3-digit) / PUG (3-digit) / Type (10-digit)

2 Type of change

- Change of markings

3 Detailed description of change

Enlarge the markings on the fuse holder.

Old product appearance	New product appearance
	

4 Reason of change

- Better readability of the markings

5 Release date

The change will be rolled-out starting ww 10/2020 (Date code 2010 or higher on label).

6 Impact of change and recommended action

Form	Yes	No further action recommended
Fit	No	No change for dimension
Function	No	No change in function
Manufacturing	No	No change for manufacturing site
Label	No	No change on label
Packaging	No	No change in packaging

7 Reference Documents / Attachments

Kind of document	Remarks
Data Sheet	FAS fuse holder

Product Change Notification					FAS inscription		
owner	creation date	release date	released by	change order no	rev	page	D10-040-167
dislercy	07.10.2019	18.12.2019	haeckima	2018490	A	1 of 1	