

1 Products affected

Product hierarchy no. *			Part no.	SBU	Type / Description	Customer part no.
SBU / PG	PGU	Type				
02	007	060	0000002252	See list below	Strip Block	4752

*SBU (2-digit) / PG (3-digit) / PGU (3-digit) / Type (10-digit)

List of part numbers affected							
4752.3000	4752.3200	4752.3400	4752.4000	4752.4200	4752.4400	4752.5000	4752.5200
4752.5400	4752.6000	4752.6200	4752.6400	4752.7000	4752.7200	4752.7400	4752.8000
4752.8200	4752.8400						


2 Type of change

Modification of approval marks.
Slight modification on the lateral indentation.


3 Detailed description of change

New combined cURus approval mark instead of separate UR and CSA marks.
Slight modification on the lateral indentation.


Old marking




New marking



Old form



New form



4752 Strip Block					0118.2240	
creation date	created by	release date	released by	notification no.	revision	page
2014-09-11	hotzar	2015-02-17	hotzar	27061	-	1 of 2

4 Reason of change

Consolidation of North American approval marks with the combined cURus mark.
Slight modification on the lateral indentation because of optimization of the injection process.

5 Release date

The change will be rolled-out individually by all part numbers affected starting ww 12/2015 and last approx. 12 months.

6 Impact of change and recommended action

Form: Yes Slight modification on the lateral indentation.
Fit: No There are no dimensional changes.
Function: No No change on the specification.
Production Site: No There is no change of the production site.
Product Label: Yes CSA and UR marks replaced by cURus mark.

7 Reference Documents / Attachments

Kind of document	Document number	Remarks
Data Sheet 4752		

4752 Strip Block					0118.2240	
creation date	created by	release date	released by	notification no.	revision	page
2014-09-11	hotzar	2015-02-17	hotzar	27061	-	2 of 2