



159 Ort Lane
Merlin, OR, US 97532
Phone: + 1 541 471 6256
Fax: + 1 541 471 6251
www.linxtechnologies.com

December 6, 2012

To: All customers using the ANT-2.4-YG6-N, ANT-2.4-YG12-N, ANT-418-YG5-N and ANT-916-YG5-N antennas

Re: End of life notice

Dear customer,

Linx Technologies discontinuing production of the ANT-2.4-YG6-N, ANT-2.4-YG12-N, ANT-418-YG5-N and ANT-916-YG5-N antennas.

We will continue to supply products to customers as stock allows. These parts are not recommended for new designs.

Parts may be scheduled for delivery up to six months after the last time buy date on a non-cancellable, non-refundable basis, depending on availability.

We are committed to working closely with our customers during this discontinuation. Please contact Linx if you have questions, concerns or would like more information.

End of Life Notice for ANT-2.4-YG6-N, ANT-2.4-YG12-N, ANT-418-YG5-N and ANT-916-YG5-N Antennas

PCN #: LEOL-121206-12

Publish Date: December 6, 2012

Type of Change

End of life

Products Affected

- ANT-2.4-YG6-N
- ANT-2.4-YG12-N
- ANT-418-YG5-N
- ANT-916-YG5-N

Description of Change

End of life notice for ANT-2.4-YG6-N, ANT-2.4-YG12-N, ANT-418-YG5-N and ANT-916-YG5-N

Reason for Change

End of life

Effect of Change

Production on the ANT-2.4-YG6-N, ANT-2.4-YG12-N, ANT-418-YG5-N and ANT-916-YG5-N antennas will cease. We will continue to supply products to customers as stock allows. Parts may be scheduled for delivery up to six months after the last time buy date on a non-cancellable, non-refundable basis, depending on availability. The parts are not recommended for new designs.

There are currently no drop-in replacements for the ANT-2.4-YG6-N, ANT-2.4-YG12-N, ANT-418-YG5-N and ANT-916-YG5-N antennas.

Anticipated Last Ship Date

April 2013 or as stock allows

Qualification Data

N/A

Last Time Buy Date

No formal last time buy date is established