

To : Dear Valued Customers

Product Discontinuance Notice

Subject : Products discontinue.															
Parts Affected :															
<table border="1" style="width: 100%; border-collapse: collapse;"> <thead> <tr> <th style="padding: 5px;">Part No.</th> <th style="padding: 5px;">Package Type</th> </tr> </thead> <tbody> <tr> <td style="text-align: center; padding: 5px;">CPDA10R5V0P-HF</td> <td style="text-align: center; padding: 5px;">DFN10P</td> </tr> <tr> <td style="text-align: center; padding: 5px;">CPDA10R5V0SP-HF</td> <td style="text-align: center; padding: 5px;">DFN10P</td> </tr> <tr> <td style="text-align: center; padding: 5px;">ACPDQC5V0USP-IPHF</td> <td style="text-align: center; padding: 5px;">0402C/SOD-923F</td> </tr> <tr> <td style="text-align: center; padding: 5px;">CPDQC5V0USP-IPHF</td> <td style="text-align: center; padding: 5px;">0402C/SOD-923F</td> </tr> <tr> <td style="text-align: center; padding: 5px;">ACPDQC5V0CSP-IPHF</td> <td style="text-align: center; padding: 5px;">0402C/SOD-923F</td> </tr> <tr> <td style="text-align: center; padding: 5px;">CPDQC5V0CSP-IPHF</td> <td style="text-align: center; padding: 5px;">0402C/SOD-923F</td> </tr> </tbody> </table>	Part No.	Package Type	CPDA10R5V0P-HF	DFN10P	CPDA10R5V0SP-HF	DFN10P	ACPDQC5V0USP-IPHF	0402C/SOD-923F	CPDQC5V0USP-IPHF	0402C/SOD-923F	ACPDQC5V0CSP-IPHF	0402C/SOD-923F	CPDQC5V0CSP-IPHF	0402C/SOD-923F	
Part No.	Package Type														
CPDA10R5V0P-HF	DFN10P														
CPDA10R5V0SP-HF	DFN10P														
ACPDQC5V0USP-IPHF	0402C/SOD-923F														
CPDQC5V0USP-IPHF	0402C/SOD-923F														
ACPDQC5V0CSP-IPHF	0402C/SOD-923F														
CPDQC5V0CSP-IPHF	0402C/SOD-923F														
Reason for Discontinuance :															
Due to the wafer supplier has suddenly shut down, the part listed will be discontinued.															
Alternative Products :															
<table border="1" style="width: 100%; border-collapse: collapse;"> <thead> <tr> <th style="padding: 5px;">EOL p/n.</th> <th style="padding: 5px;">Alternative p/n</th> </tr> </thead> <tbody> <tr> <td style="text-align: center; padding: 5px;">CPDA10R5V0P-HF</td> <td rowspan="2" style="text-align: center; padding: 5px;">Please contact sales person or manufacturer's representative.</td> </tr> <tr> <td style="text-align: center; padding: 5px;">CPDA10R5V0SP-HF</td> </tr> <tr> <td style="text-align: center; padding: 5px;">ACPDQC5V0USP-IPHF</td> <td style="text-align: center; padding: 5px;">CPDQC5V0USC-HF</td> </tr> <tr> <td style="text-align: center; padding: 5px;">CPDQC5V0USP-IPHF</td> <td rowspan="3" style="text-align: center; padding: 5px;">CPDQC5V0SC-HF</td> </tr> <tr> <td style="text-align: center; padding: 5px;">ACPDQC5V0CSP-IPHF</td> </tr> <tr> <td style="text-align: center; padding: 5px;">CPDQC5V0CSP-IPHF</td> </tr> </tbody> </table>	EOL p/n.	Alternative p/n	CPDA10R5V0P-HF	Please contact sales person or manufacturer's representative.	CPDA10R5V0SP-HF	ACPDQC5V0USP-IPHF	CPDQC5V0USC-HF	CPDQC5V0USP-IPHF	CPDQC5V0SC-HF	ACPDQC5V0CSP-IPHF	CPDQC5V0CSP-IPHF				
EOL p/n.	Alternative p/n														
CPDA10R5V0P-HF	Please contact sales person or manufacturer's representative.														
CPDA10R5V0SP-HF															
ACPDQC5V0USP-IPHF	CPDQC5V0USC-HF														
CPDQC5V0USP-IPHF	CPDQC5V0SC-HF														
ACPDQC5V0CSP-IPHF															
CPDQC5V0CSP-IPHF															
Effective Date :															
Comchip will continue to ship the materials before replacement until inventory is depleted.															
R&D Dept. Signature :	QA Dept. Signature :														