



Product Discontinuance Notice - PDN 17_0069 Rev. -

Analog Devices, Inc. Three Technology Way Norwood, Massachusetts 02062-9106

This notice is to inform you of a product discontinuance for certain ADI products (see Discontinued Parts Material List below). Any issues with this PDN must be sent to ADI as soon as possible. The information contained within this PDN is considered proprietary and should not be shared outside of your company. ADI contact information is listed below.

PDN Title:

Obsolescence of Lead (Pb)-Bearing Packages

Publication Date: 19-Dec-2017

Last Time Buy Date: 22-Jun-2018

Last Time Ship Date: 19-Dec-2019

Revision Description:

Revise the last time buy date due to Supplier end of service on the line

Reason For Discontinuance

ADI's suppliers have announced that they will discontinue support of SnPb plating for most packages.

With the industry transition to Pb-free packages nearing completion, the demand for Pb-bearing packages is minimal.

Supporting Documents None

For questions on this PDN, send email to the regional contacts below or contact your local ADI sales representative

Americas: PDN_Americas@analog.com

Europe: PDN_Europe@analog.com

Japan: PDN_Japan@analog.com

Rest of Asia: PDN_ROA@analog.com

PDN 17_0069 Discontinued Parts Material List

Model	Product Family	Replacement Part	Pin To Pin Compatible	Comments
AD1671JP	AD1671	AD9243ASZ	NO	Not a compatible match, but customer can easily switch
AD1671KP	AD1671	AD9243ASZ	NO	Not a compatible match, but customer can easily switch
AD42941	AD1671	AD9243ASZ	NO	Not a compatible match, but customer can easily switch
AD9218BST-105	AD9218	AD9218BSTZ-105	YES	
AD9218BST-RL105	AD9218	AD9218BSTZ-RL105	YES	
AD9240AS	AD9240	AD9240ASZ	YES	
AD9765AST	AD9765	AD9765ASTZ	YES	

Appendix A - PDN 17_0069 Revision History

Rev	Publish Date	Rev Description
Rev. -	19-Dec-2017	Revise the last time buy date due to Supplier end of service on the line

Analog Devices, Inc. Proprietary Information

DocId:1203 Layout Rev:2 Parent DocId:None