Panasonic



Not Recommended for New Design: AQZ262 and AQZ264 High Capacity PhotoMOS Relays

NRFND.PG0001.12.21.2018 12.21.2018

About This Notice:	Newer generation product has be introduced to the market from Panasonic.
Features:	
Effective Date:	Immediate
Affected Parts and/or Replacements:	AQZ262 and AQZ264
Datasheet(s):	See attached
Notes:	The AQZ262 should be replaced by the AQZ202G. The AQZ264 should be replaced by the AQZ206G2.