

## Product Change Notification

### INDUCTIVE COMPONENTS



December, 2016

## Bourns® Model FB2000 Series Wide-Band Chokes

### Change to Core Design

Bourns has changed the core design of the [Model FB2000 Series](#) Wide-Band Chokes starting with the manufacturing date code 1629. Chamfers are included at both ends of the core to reduce the possibility of material chipping during production assembly. See Table 1 for details.

This core modification will not affect the form, fit or function of the wide-band choke. However, the quality and reliability of the component should be enhanced.

| Table 1 |                    |                                |
|---------|--------------------|--------------------------------|
| Series  | Current            | Revised                        |
| FB2000  | <p>Right Angle</p> | <p>0.25 mm (Ref.) Chamfers</p> |
|         |                    |                                |

| Affected Part Numbers |               |
|-----------------------|---------------|
| FB20009-3B-RC         | FB20011-3B-RC |
| FB20019-4B-RC         | FB20021-4B-RC |
| FB20010-3B-RC         | FB20022-4B-RC |
| FB20020-4B-RC         |               |

If you have any questions or need additional information, please feel free to contact [Customer Service/ Inside Sales](#).