



Harwin plc
Fitzherbert Road
Farlington, Portsmouth
Hampshire PO6 1RT
United Kingdom

Reception: +44 (0)23 9231 4545
Sales Desk: +44 (0)23 9237 0451
Fax: +44 (0)23 9231 4590

Wednesday 23rd December, 2015

Dear Customer,

Re: Obsolescence notification for Harwin product.

Please be advised that there are a number of 44-contact Datamate L-Tek SMT connectors that are now obsolete. These items are **obsolete with immediate effect**; stocks may remain of a few items, but most of these have not been manufactured. Please see the attached spreadsheet for a complete list of affected items. Here is a summary of affected standard ranges:

- M80-665xxxx – 44-contact
- M80-666xxxx – 44-contact
- M80-667xxxx – 44-contact
- M80-826xxxx and M80-826xxxxP – 44-contact
- M80-827xxxx and M80-827xxxxP – 44-contact
- M80-828xxxx and M80-828xxxxP – 44-contact

Unfortunately, we are no longer able to support these product lines.

If you have any further questions regarding this letter, please do not hesitate to contact us.

Yours faithfully,

The Product Management Team
technical@harwin.com

If you have not been sent the accompanying spreadsheet, please request it from the contact that sent you this letter.