

PRODUCT CHANGE NOTIFICATION

Product Category _____ **20191115**

Product Group Product Lifecycle Management - Product Change Notification (North America Only)

ISSUE DATE: _____

IMPACTED REGIONS: NA EMEA LATAM AP

REASON FOR CHANGE: DISCONTINUATION
 OTHER

DESCRIPTION OF CHANGE: (Required)

Based on 80/20 initiative, products from several product lines are being discontinued and will no longer be available after 12/31/19. The parts listed may or may not include replacement recommendations.

Photos/Drawing (where applicable)

IMPACTED PART NUMBERS AND REPLACEMENT PART NUMBERS: (where applicable)

[Reference Page 2 / Linked PDF](#)

DATES: DISCONTINUATION AND NEW PRODUCT AVAILABILITY:

| SCHEDULE FOR CHANGE | Year (YYYY) | Month (MM) | Day (DD) |
|--------------------------------------|-------------|------------|----------|
| New product sample availability date | | | |
| Old product discontinuation date* | 2019 | 12 | 31 |

***Important:** A return material authorization (RMA) may be obtained for the affected part numbers listed above if purchased within the last 18 months and subject to the return policy requirements outlined in Panduit's 1/1/19 Authorized Distributor Policy. Please contact your local Panduit Customer Experience team if you have any questions.

| IMPACTED PART NUMBER(s) | Replacement Part 1 |
|-------------------------|--------------------|
| PUO3025BL-V | No Replacement |
| PUR3025WH-A | No Replacement |
| PUR3050WH-A | No Replacement |
| PFC5504BU-G-L | No Replacement |
| PFC5504IG-KG | No Replacement |
| PFL5504DG-KD | No Replacement |
| PFL5504IG-G | No Replacement |
| PFL5504WH-G | No Replacement |
| PFL5504WH-KD | No Replacement |
| PUC50100WH-A | No Replacement |
| PUC5025WH-AH | No Replacement |
| PUC5504BL-EY | No Replacement |
| PUC5504BLY | No Replacement |
| PUC5504BU-EY | No Replacement |
| PUC5504GR-EY | No Replacement |
| PUC5504IGY-L | No Replacement |
| PUC5504OR-EY | No Replacement |
| PUC5504ORY | No Replacement |
| PUC5504RD-EY | No Replacement |
| PUC5504VL-EY | No Replacement |
| PUC5504VLY | No Replacement |
| PUC5504WH-EY | No Replacement |
| PUC5504YL-EY | No Replacement |
| PUC5C04PB-C | No Replacement |
| PUC5C04PG-C | No Replacement |
| PUL5504BL-EY | No Replacement |
| PUL5504BU-EY | No Replacement |
| PUL5504GR-EY | No Replacement |
| PUL5504OR-EY | No Replacement |
| PUL5504RD-EY | No Replacement |
| PUL5504VL-EY | No Replacement |
| PUL5504YL-EY | No Replacement |
| PUP5504BU-U | No Replacement |
| PUP5504BU-UTY | No Replacement |
| PUP5504WH-UTY | No Replacement |
| PUR5025WH-A | No Replacement |
| PUR5050WH-A | No Replacement |
| PUR5504BLY | No Replacement |
| PUR5504BU-UTY | No Replacement |
| PUR5504GRY | No Replacement |
| PUR5504ORY | No Replacement |
| PUR5504RDY | No Replacement |
| PUR5504VLY | No Replacement |
| PUR5504WH-UTY | No Replacement |
| PUR5504WHY | No Replacement |
| PUZ5504BL-CED | No Replacement |

| | |
|---------------|----------------|
| PUZ5504BL-CEG | No Replacement |
| PUZ5504GR-CED | No Replacement |
| PUZ5504GR-CEG | No Replacement |
| PUZ5504IG-CED | No Replacement |
| PUZ5504IG-CEG | No Replacement |
| PUZ5504OR-CED | No Replacement |
| PUZ5504OR-CEG | No Replacement |
| PUZ5504RD-CED | No Replacement |
| PUZ5504RD-CEG | No Replacement |
| PUZ5504VL-CED | No Replacement |
| PUZ5504VL-CEG | No Replacement |
| PUZ5504WH-CED | No Replacement |
| PUZ5504YL-CED | No Replacement |
| PUZ5504YL-CEG | No Replacement |
| PFV6C04DG-PED | No Replacement |
| PFV6C04LG-PED | No Replacement |
| PFY6C04BL-CED | No Replacement |
| PFY6C04BU-CED | No Replacement |
| PFY6C04GR-CED | No Replacement |
| PFY6C04IG-CED | No Replacement |
| PFY6C04OR-CED | No Replacement |
| PFY6C04RD-CED | No Replacement |
| PFY6C04VL-CED | No Replacement |
| PFY6C04WH-CED | No Replacement |
| PFY6C04YL-CED | No Replacement |
| PFZ6C04BL-CED | No Replacement |
| PFZ6C04BU-CED | No Replacement |
| PFZ6C04GR-CED | No Replacement |
| PFZ6C04IG-CED | No Replacement |
| PFZ6C04OR-CED | No Replacement |
| PFZ6C04RD-CED | No Replacement |
| PFZ6C04VL-CED | No Replacement |
| PFZ6C04YL-CED | No Replacement |
| PSY6C04BL-CED | No Replacement |
| PSY6C04BU-CED | No Replacement |
| PSY6C04GR-CED | No Replacement |
| PSY6C04IG-CED | No Replacement |
| PSY6C04OR-CED | No Replacement |
| PSY6C04RD-CED | No Replacement |
| PSY6C04VL-CED | No Replacement |
| PSY6C04YL-CED | No Replacement |
| PUC6004BL-CE | No Replacement |
| PUC6004BL-EY | No Replacement |
| PUC6004BU-CE | No Replacement |
| PUC6004BU-EY | No Replacement |
| PUC6004GR-CE | No Replacement |
| PUC6004GR-EY | No Replacement |

| | |
|----------------|----------------|
| PUC6004IG-CE | No Replacement |
| PUC6004IG-J | No Replacement |
| PUC6004OR-CE | No Replacement |
| PUC6004OR-EY | No Replacement |
| PUC6004RD-CE | No Replacement |
| PUC6004RD-EY | No Replacement |
| PUC6004VL-CE | No Replacement |
| PUC6004VL-EY | No Replacement |
| PUC6004VL-FE | No Replacement |
| PUC6004WH-CE | No Replacement |
| PUC6004WH-EY | No Replacement |
| PUC6004YL-CE | No Replacement |
| PUC6004YL-EY | No Replacement |
| PUC6C04BL-CE | No Replacement |
| PUC6C04BU-CE | No Replacement |
| PUC6C04GR-CE | No Replacement |
| PUC6C04OR-CE | No Replacement |
| PUC6C04PB-C | No Replacement |
| PUC6C04PG-C | No Replacement |
| PUC6C04RD-CE | No Replacement |
| PUC6C04VL-CE | No Replacement |
| PUC6C04WH-CE | No Replacement |
| PUC6C04YL-CE | No Replacement |
| PUD6C2804OR-CE | No Replacement |
| PUD6C2804VL-CE | No Replacement |
| PUL6004IG-EDY | No Replacement |
| PUL6004OR-EY | No Replacement |
| PUL6004RD-EY | No Replacement |
| PUL6004VL-EY | No Replacement |
| PUL6C04BL-C | No Replacement |
| PUL6C04BL-CE | No Replacement |
| PUL6C04BL-FE | No Replacement |
| PUL6C04BL-KE | No Replacement |
| PUL6C04BL-KED | No Replacement |
| PUL6C04BL-KEG | No Replacement |
| PUL6C04BU-CE | No Replacement |
| PUL6C04BU-FE | No Replacement |
| PUL6C04BU-KE | No Replacement |
| PUL6C04BU-KED | No Replacement |
| PUL6C04GR-CE | No Replacement |
| PUL6C04GR-FE | No Replacement |
| PUL6C04GR-KE | No Replacement |
| PUL6C04GR-KED | No Replacement |
| PUL6C04GY-KED | No Replacement |
| PUL6C04IG-CE | No Replacement |
| PUL6C04IG-FE | No Replacement |
| PUL6C04IG-KE | No Replacement |

| | |
|-----------------|----------------|
| PUL6C04IG-KED | No Replacement |
| PUL6C04OR-CE | No Replacement |
| PUL6C04OR-FE | No Replacement |
| PUL6C04OR-KE | No Replacement |
| PUL6C04OR-KED | No Replacement |
| PUL6C04RD-C | No Replacement |
| PUL6C04RD-CE | No Replacement |
| PUL6C04RD-FE | No Replacement |
| PUL6C04RD-KE | No Replacement |
| PUL6C04RD-KED | No Replacement |
| PUL6C04VL-C | No Replacement |
| PUL6C04VL-CE | No Replacement |
| PUL6C04VL-FE | No Replacement |
| PUL6C04VL-KE | No Replacement |
| PUL6C04VL-KED | No Replacement |
| PUL6C04WH-FE | No Replacement |
| PUL6C04WH-KED | No Replacement |
| PUL6C04YL-CE | No Replacement |
| PUL6C04YL-FE | No Replacement |
| PUL6C04YL-KE | No Replacement |
| PUL6C04YL-KED | No Replacement |
| PUR6004BL-FE | No Replacement |
| PUR6004VL-FE | No Replacement |
| PUR6C04BL-C | No Replacement |
| PUR6C04GR-C | No Replacement |
| PUR6C04IG-C | No Replacement |
| PUR6C04OR-C | No Replacement |
| PUR6C04RD-C | No Replacement |
| PUR6C04VL-C | No Replacement |
| PUR6C04WH-C | No Replacement |
| PUR6C04YL-C | No Replacement |
| PUR6C2804BL-CE | No Replacement |
| PUR6C2804BL-CES | No Replacement |
| PUR6C2804BU-CE | No Replacement |
| PUR6C2804BU-CES | No Replacement |
| PUR6C2804GR-CE | No Replacement |
| PUR6C2804GR-CES | No Replacement |
| PUR6C2804IG-CE | No Replacement |
| PUR6C2804IG-CES | No Replacement |
| PUR6C2804OR-CE | No Replacement |
| PUR6C2804OR-CES | No Replacement |
| PUR6C2804RD-CE | No Replacement |
| PUR6C2804RD-CES | No Replacement |
| PUR6C2804VL-CE | No Replacement |
| PUR6C2804VL-CES | No Replacement |
| PUR6C2804WH-CE | No Replacement |
| PUR6C2804WH-CES | No Replacement |

| | |
|-----------------|----------------|
| PUR6C2804YL-CE | No Replacement |
| PUR6C2804YL-CES | No Replacement |
| PUY6C04BL-CED | No Replacement |
| PUY6C04IG-CE | No Replacement |
| PUY6C04IG-CED | No Replacement |
| PUY6C04OR-CED | No Replacement |
| PUY6C04RD-CE | No Replacement |
| PUY6C04RD-CED | No Replacement |
| PUY6C04VL-CE | No Replacement |
| PUY6C04VL-CED | No Replacement |
| PUZ6004BL-CED | No Replacement |
| PUZ6004BL-CEG | No Replacement |
| PUZ6004GR-CED | No Replacement |
| PUZ6004IG-CED | No Replacement |
| PUZ6004OR-CED | No Replacement |
| PUZ6004OR-CEG | No Replacement |
| PUZ6004RD-CED | No Replacement |
| PUZ6004RD-CEG | No Replacement |
| PUZ6004VL-CED | No Replacement |
| PUZ6004VL-CEG | No Replacement |
| PUZ6004WH-CED | No Replacement |
| PUZ6004YL-CED | No Replacement |
| NUC5C04BL-C | No Replacement |
| NUC5C04BL-CE | No Replacement |
| NUC5C04GR-CE | No Replacement |
| NUC5C04OR-C | No Replacement |
| NUC5C04OR-CE | No Replacement |
| NUC5C04RD-CE | No Replacement |
| NUC5C04VL-C | No Replacement |
| NUC5C04VL-CE | No Replacement |
| NUC5C04WH-C | No Replacement |
| NUC5C04YL-C | No Replacement |
| NUC5C04YL-CE | No Replacement |
| NUL5C04BL-C | No Replacement |
| NUL5C04GR-C | No Replacement |
| NUL5C04GR-CE | No Replacement |
| NUL5C04IG-CE | No Replacement |
| NUL5C04OR-CE | No Replacement |
| NUL5C04RD-C | No Replacement |
| NUL5C04RD-CE | No Replacement |
| NUL5C04VL-C | No Replacement |
| NUL5C04VL-CE | No Replacement |
| NUL5C04YL-C | No Replacement |
| NUL5C04YL-CE | No Replacement |
| NUR5C04BL-C | No Replacement |
| NUR5C04GR-C | No Replacement |
| NUR5C04OR-C | No Replacement |

| | |
|---------------|----------------|
| NUR5C04RD-C | No Replacement |
| NUR5C04VL-C | No Replacement |
| NUR5C04YL-C | No Replacement |
| NUC6004BU-C | No Replacement |
| NUC6004IG-C | No Replacement |
| NUC6C04BL-C | No Replacement |
| NUC6C04BL-CE | No Replacement |
| NUC6C04BL-PE | No Replacement |
| NUC6C04BU-PE | No Replacement |
| NUC6C04GR-PE | No Replacement |
| NUC6C04IG-PE | No Replacement |
| NUC6C04OR-CE | No Replacement |
| NUC6C04OR-PE | No Replacement |
| NUC6C04RD-CE | No Replacement |
| NUC6C04RD-PE | No Replacement |
| NUC6C04VL-C | No Replacement |
| NUC6C04VL-CE | No Replacement |
| NUC6C04VL-PE | No Replacement |
| NUC6C04WH-CE | No Replacement |
| NUC6C04WH-PE | No Replacement |
| NUC6C04YL-CE | No Replacement |
| NUC6C04YL-PE | No Replacement |
| NUC6CR04BL-CE | No Replacement |
| NUC6CR04OR-CE | No Replacement |
| NUC6CR04VL-CE | No Replacement |
| NUL6C04BL-C | No Replacement |
| NUL6C04BL-CE | No Replacement |
| NUL6C04BL-FE | No Replacement |
| NUL6C04BL-KE | No Replacement |
| NUL6C04BU-FE | No Replacement |
| NUL6C04GR-C | No Replacement |
| NUL6C04GR-CE | No Replacement |
| NUL6C04GR-FE | No Replacement |
| NUL6C04GR-KE | No Replacement |
| NUL6C04IG-CE | No Replacement |
| NUL6C04IG-FE | No Replacement |
| NUL6C04IG-KE | No Replacement |
| NUL6C04OR-C | No Replacement |
| NUL6C04OR-CE | No Replacement |
| NUL6C04OR-FE | No Replacement |
| NUL6C04OR-KE | No Replacement |
| NUL6C04RD-C | No Replacement |
| NUL6C04RD-CE | No Replacement |
| NUL6C04RD-FE | No Replacement |
| NUL6C04RD-KE | No Replacement |
| NUL6C04VL-C | No Replacement |
| NUL6C04VL-FE | No Replacement |

| | |
|---------------|----------------|
| NUL6C04WH-FE | No Replacement |
| NUL6C04YL-C | No Replacement |
| NUL6C04YL-CE | No Replacement |
| NUL6C04YL-FE | No Replacement |
| NUL6C04YL-KE | No Replacement |
| NUL6CR04BL-CE | No Replacement |
| NUL6CR04GR-CE | No Replacement |
| NUL6CR04OR-CE | No Replacement |
| NUL6CR04RD-CE | No Replacement |
| NUL6CR04VL-CE | No Replacement |
| NUR6C04BL-C | No Replacement |
| NUR6C04GR-C | No Replacement |
| NUR6C04OR-C | No Replacement |
| NUR6C04RD-C | No Replacement |
| NUR6C04VL-C | No Replacement |
| NUR6C04WH-C | No Replacement |
| NUR6C04YL-C | No Replacement |
| NUR6CR04BL-CE | No Replacement |
| NUR6CR04BU-CE | No Replacement |
| NUR6CR04GR-CE | No Replacement |
| NUR6CR04IG-CE | No Replacement |
| NUR6CR04OR-CE | No Replacement |
| NUR6CR04RD-CE | No Replacement |
| NUR6CR04VL-CE | No Replacement |
| NUR6CR04WH-CE | No Replacement |
| NUV6C04BL-PE | No Replacement |
| NUV6C04BU-PE | No Replacement |
| NUV6C04GR-PE | No Replacement |
| NUV6C04IG-PE | No Replacement |
| NUV6C04OR-PE | No Replacement |
| NUV6C04RD-PE | No Replacement |
| NUV6C04VL-PE | No Replacement |
| NUV6C04WH-PE | No Replacement |
| NUV6C04YL-PE | No Replacement |
| NUY6C04BL-CE | No Replacement |
| NUY6C04GR-CE | No Replacement |
| NUY6C04IG-CE | No Replacement |
| NUY6C04OR-CE | No Replacement |
| NUY6C04RD-CE | No Replacement |
| NUY6C04VL-CE | No Replacement |
| NUY6C04YL-CE | No Replacement |
| NUZ6C04BL-CE | No Replacement |
| NUZ6C04BU-CE | No Replacement |
| NUZ6C04GR-CE | No Replacement |
| NUZ6C04IG-CE | No Replacement |
| NUZ6C04OR-CE | No Replacement |
| NUZ6C04RD-CE | No Replacement |

| | |
|-----------------|----------------|
| NUZ6C04VL-CE | No Replacement |
| NUZ6C04WH-CE | No Replacement |
| NUZ6C04YL-CE | No Replacement |
| NUL6X04BL-CEG | No Replacement |
| NUL6X04GR-CEG | No Replacement |
| NUL6X04OR-CEG | No Replacement |
| NUL6X04RD-CEG | No Replacement |
| NUL6X04VL-CEG | No Replacement |
| NUL6X04YL-CEG | No Replacement |
| PFC6X04BL-CEG | No Replacement |
| PFC6X04GR-CEG | No Replacement |
| PFC6X04IG-CEG | No Replacement |
| PFC6X04OR-CEG | No Replacement |
| PFC6X04RD-CEG | No Replacement |
| PFC6X04VL-CEG | No Replacement |
| PFC6X04YL-CEG | No Replacement |
| PFZ6X04WH-CED | No Replacement |
| PUL6A04BL-KEG | No Replacement |
| PUL6A04BU-KEG | No Replacement |
| PUL6A04GR-KEG | No Replacement |
| PUL6A04IG-KEG | No Replacement |
| PUL6A04OR-KEG | No Replacement |
| PUL6A04RD-KEG | No Replacement |
| PUL6A04VL-KEG | No Replacement |
| PUL6A04YL-KEG | No Replacement |
| PUL6AM04BL-CED | No Replacement |
| PUL6ASD04BL-CED | No Replacement |
| PUL6ASD04BL-EG | No Replacement |
| PUL6ASD04BU-CED | No Replacement |
| PUL6ASD04GR-CED | No Replacement |
| PUL6ASD04IG-CED | No Replacement |
| PUL6ASD04IG-EG | No Replacement |
| PUL6ASD04OR-CED | No Replacement |
| PUL6ASD04OR-EG | No Replacement |
| PUL6ASD04RD-CED | No Replacement |
| PUL6ASD04VL-CED | No Replacement |
| PUL6ASD04VL-EG | No Replacement |
| PUL6ASD04WH-CED | No Replacement |
| PUL6ASD04YL-CED | No Replacement |
| PUL6ASD04YL-EG | No Replacement |
| PUP6AM04BL-UGA | No Replacement |
| PUP6AM04GR-UGA | No Replacement |
| PUP6AM04IG-UGA | No Replacement |
| PUP6AM04OR-UGA | No Replacement |
| PUP6AM04RD-UGA | PUP6AV04RD-G |
| PUP6AM04VL-UGA | No Replacement |
| PUP6AM04YL-UGA | PUP6AV04YL-G |

| | |
|-----------------|----------------|
| PUZ6AM04BL-CED | No Replacement |
| PUZ6AM04BL-CEG | No Replacement |
| PUZ6AM04GR-CED | No Replacement |
| PUZ6AM04GR-CEG | No Replacement |
| PUZ6AM04IG-CED | No Replacement |
| PUZ6AM04IG-CEG | No Replacement |
| PUZ6AM04OR-CED | No Replacement |
| PUZ6AM04OR-CEG | No Replacement |
| PUZ6AM04RD-CED | No Replacement |
| PUZ6AM04RD-CEG | No Replacement |
| PUZ6AM04VL-CED | No Replacement |
| PUZ6AM04VL-CEG | No Replacement |
| PUZ6AM04WH-CED | No Replacement |
| PUZ6AM04YL-CED | No Replacement |
| PUZ6AM04YL-CEG | No Replacement |
| PUZ6ASD04BU-EGS | No Replacement |
| PUZ6ASD04IG-EG | No Replacement |
| PUZ6ASD04WH-CED | No Replacement |
| PFFL6X04BL-CED | No Replacement |
| PFFL6X04BU-CED | No Replacement |
| PFFL6X04GR-CED | No Replacement |
| PFFL6X04OR-CED | No Replacement |
| PFFL6X04RD-CED | No Replacement |
| PFFL6X04VL-CED | No Replacement |
| PFFL6X04YL-CED | No Replacement |
| PFFY6X04WH-HEG | No Replacement |
| PFFZ6X04BU-CEDS | No Replacement |
| PFL6X04GR-CEG | No Replacement |
| PFL6X04OR-CEG | No Replacement |
| PFL6X04VL-CEG | No Replacement |
| PFL6X0GR4-CEG | No Replacement |
| PFZ6X04BL-CEG | No Replacement |
| PFZ6X04BU-CED-S | No Replacement |
| PFZ6X04GR-CEG | No Replacement |
| PFZ6X04OR-CEG | No Replacement |
| PFZ6X04RD-CEG | No Replacement |
| PFZ6X04VL-CEG | No Replacement |
| PFZ6X04WH-CED | No Replacement |
| PFZ6X04YL-CEG | No Replacement |
| PSL27A2204BL-HD | No Replacement |
| PSL27A2204BU-HD | No Replacement |
| PSL27A2204GR-HD | No Replacement |
| PSL27A2204IG-HD | No Replacement |
| PSL27A2204OR-HD | No Replacement |
| PSL27A2204RD-HD | No Replacement |
| PSL27A2204VL-HD | No Replacement |
| PSL27A2204WH-HD | No Replacement |

| | |
|-----------------|----------------|
| PSL27A2204YL-HD | No Replacement |
| PSL7004BL-HED | No Replacement |
| PSL7004BU-HED | No Replacement |
| PSL7004GR-CED | No Replacement |
| PSL7004GR-HED | No Replacement |
| PSL7004IG-HED | No Replacement |
| PSL7004IG-KD | No Replacement |
| PSL7004OR-CED | No Replacement |
| PSL7004OR-HED | No Replacement |
| PSL7004RD-CED | No Replacement |
| PSL7004RD-HED | No Replacement |
| PSL7004VL-CED | No Replacement |
| PSL7004VL-HED | No Replacement |
| PSL7004WH-HED | No Replacement |
| PSL7004YL-CED | No Replacement |
| PSL7004YL-HED | No Replacement |
| PSL7A04BL-HED | No Replacement |
| PSL7A04BL-KD | No Replacement |
| PSL7A04BU-HED | No Replacement |
| PSL7A04GR-HED | No Replacement |
| PSL7A04GR-KD | No Replacement |
| PSL7A04IG-HED | No Replacement |
| PSL7A04IG-KD | No Replacement |
| PSL7A04OR-HED | No Replacement |
| PSL7A04OR-KD | No Replacement |
| PSL7A04RD-HED | No Replacement |
| PSL7A04RD-KD | No Replacement |
| PSL7A04VL-HED | No Replacement |
| PSL7A04VL-KD | No Replacement |
| PSL7A04WH-HED | No Replacement |
| PSL7A04YL-HED | No Replacement |
| PSL7A04YL-KD | No Replacement |
| PSL7A2204BL-HED | No Replacement |
| PSL7A2204BU-HED | No Replacement |
| PSL7A2204GR-HED | No Replacement |
| PSL7A2204IG-HED | No Replacement |
| PSL7A2204OR-HED | No Replacement |
| PSL7A2204RD-HED | No Replacement |
| PSL7A2204VL-HED | No Replacement |
| PSL7A2204WH-HED | No Replacement |
| PSL7A2204YL-HED | No Replacement |
| PUFL6X04BL-KD | No Replacement |
| PUFL6X04BU-KD | No Replacement |
| PUFL6X04GR-KD | No Replacement |
| PUFL6X04IG-KD | No Replacement |
| PUFL6X04OR-KD | No Replacement |
| PUFL6X04RD-KD | No Replacement |

| | |
|---------------|----------------|
| PUFL6X04VL-KD | No Replacement |
| PUFZ6X04BL-KD | No Replacement |
| PUFZ6X04GR-KD | No Replacement |
| PUFZ6X04IG-KD | No Replacement |
| PUFZ6X04OR-KD | No Replacement |
| PUFZ6X04RD-KD | No Replacement |
| PUFZ6X04VL-KD | No Replacement |
| PUFZ6X04WH-KD | No Replacement |
| PUFZ6X04YL-KD | No Replacement |
| FACC524-40 | No Replacement |
| FADC506-37 | No Replacement |
| FADC508-37 | No Replacement |
| FADC512-37 | No Replacement |
| FADC516-37 | No Replacement |
| FADC604-37 | No Replacement |
| FADC606-37 | No Replacement |
| FADC608-37 | No Replacement |
| FADC612-37 | No Replacement |
| FADC616-37 | No Replacement |
| FADC624-37 | No Replacement |
| FADC916-37 | No Replacement |
| FADCX16-37 | No Replacement |
| FADCZ04-37 | No Replacement |
| FADCZ06-37 | No Replacement |
| FADCZ16-37 | No Replacement |
| FAEC536-40 | No Replacement |
| FAEC548-40 | No Replacement |
| FAEC572-40 | No Replacement |
| FAEC596-40 | No Replacement |
| FAEC636-40 | No Replacement |
| FAEC648-40 | No Replacement |
| FAEC672-40 | No Replacement |
| FAEC696-40 | No Replacement |
| FAEC936-40 | No Replacement |
| FAEC972-40 | No Replacement |
| FAEC996-40 | No Replacement |
| FAECX36-40 | No Replacement |
| FAECX48-40 | No Replacement |
| FAECX72-40 | No Replacement |
| FAECX96-40 | No Replacement |
| FAECZ36-40 | No Replacement |
| FAECZ72-40 | No Replacement |
| FAECZ96-40 | No Replacement |
| FANC572-24 | No Replacement |
| FLCL502Y | No Replacement |
| FLCL504Y | No Replacement |
| FLCL506Y | No Replacement |

| | |
|----------|----------------|
| FLCL508Y | No Replacement |
| FLCL512Y | No Replacement |
| FLCL602Y | No Replacement |
| FLCL604Y | No Replacement |
| FLCL606Y | No Replacement |
| FLCL608Y | No Replacement |
| FLCL612Y | No Replacement |
| FLCL902Y | No Replacement |
| FLCL904Y | No Replacement |
| FLCL906Y | No Replacement |
| FLCL912Y | No Replacement |
| FLCLX02Y | No Replacement |
| FLCLX04Y | No Replacement |
| FLCLX08Y | No Replacement |
| FLCLX12Y | No Replacement |
| FLCLZ02Y | No Replacement |
| FLCLZ04Y | No Replacement |
| FLCLZ06Y | No Replacement |
| FLCLZ08Y | No Replacement |
| FLCLZ12Y | No Replacement |
| FLCR502Y | No Replacement |
| FLCR504Y | No Replacement |
| FLCR506Y | No Replacement |
| FLCR508Y | No Replacement |
| FLCR512Y | No Replacement |
| FLCR602Y | No Replacement |
| FLCR604Y | No Replacement |
| FLCR608Y | No Replacement |
| FLCR612Y | No Replacement |
| FLCR902Y | No Replacement |
| FLCR904Y | No Replacement |
| FLCRX02Y | No Replacement |
| FLCRX04Y | No Replacement |
| FLCRZ02Y | No Replacement |
| FLCRZ04Y | No Replacement |
| FLDL506Y | No Replacement |
| FLDL508Y | No Replacement |
| FLDL512Y | No Replacement |
| FLDL524Y | No Replacement |
| FLDL536Y | No Replacement |
| FLDL548Y | No Replacement |
| FLDL606Y | No Replacement |
| FLDL608Y | No Replacement |
| FLDL612Y | No Replacement |
| FLDL624Y | No Replacement |
| FLDL636Y | No Replacement |
| FLDL648Y | No Replacement |

| | |
|----------|----------------|
| FLDL936Y | No Replacement |
| FLDL948Y | No Replacement |
| FLDLX36Y | No Replacement |
| FLDLX48Y | No Replacement |
| FLDLZ08Y | No Replacement |
| FLDLZ36Y | No Replacement |
| FLDR508Y | No Replacement |
| FLDR512Y | No Replacement |
| FLDR524Y | No Replacement |
| FLDR536Y | No Replacement |
| FLDR548Y | No Replacement |
| FLDR606Y | No Replacement |
| FLDR608Y | No Replacement |
| FLDR624Y | No Replacement |
| FLDR636Y | No Replacement |
| FLDR648Y | No Replacement |
| FLDR936Y | No Replacement |
| FLDRX36Y | No Replacement |
| FLDRZ36Y | No Replacement |
| FLIL502Y | No Replacement |
| FLIL504Y | No Replacement |
| FLIL602Y | No Replacement |
| FLIL604Y | No Replacement |
| FLILV02Y | No Replacement |
| FLIR504Y | No Replacement |
| FLIR602Y | No Replacement |
| FLIRZ02Y | No Replacement |
| FLKL504 | No Replacement |
| FLKL506 | No Replacement |
| FLKL508 | No Replacement |
| FLKL512 | No Replacement |
| FLKL516 | No Replacement |
| FLKL524 | No Replacement |
| FLKL548 | No Replacement |
| FLKL572 | No Replacement |
| FLKL604 | No Replacement |
| FLKL606 | No Replacement |
| FLKL608 | No Replacement |
| FLKL612 | No Replacement |
| FLKL616 | No Replacement |
| FLKL624 | No Replacement |
| FLKL648 | No Replacement |
| FLKL672 | No Replacement |
| FLKL916 | No Replacement |
| FLKLX16 | No Replacement |
| FLKLX48 | No Replacement |
| FLKLX72 | No Replacement |

| | |
|----------|----------------|
| FLKLZ16 | No Replacement |
| FLKLZ72 | No Replacement |
| FLKR506 | No Replacement |
| FLKR512 | No Replacement |
| FLKR516 | No Replacement |
| FLKR524 | No Replacement |
| FLKR548 | No Replacement |
| FLKR572 | No Replacement |
| FLKR604 | No Replacement |
| FLKR606 | No Replacement |
| FLKR608 | No Replacement |
| FLKR612 | No Replacement |
| FLKR616 | No Replacement |
| FLKR624 | No Replacement |
| FLKR648 | No Replacement |
| FLKR672 | No Replacement |
| FLKR916 | No Replacement |
| FLKRX16 | No Replacement |
| FLKRX48 | No Replacement |
| FLKRX72 | No Replacement |
| FLKRZ08 | No Replacement |
| FLKRZ16 | No Replacement |
| FLKRZ72 | No Replacement |
| FLNL524Y | No Replacement |
| FLNL536Y | No Replacement |
| FLNL548Y | No Replacement |
| FLNL624Y | No Replacement |
| FLNL636Y | No Replacement |
| FLNL648Y | No Replacement |
| FLNL924Y | No Replacement |
| FLNLX24Y | No Replacement |
| FLNLX36Y | No Replacement |
| FLNLX48Y | No Replacement |
| FLNLZ24Y | No Replacement |
| FLNLZ36Y | No Replacement |
| FLNLZ48Y | No Replacement |
| FLNR524Y | No Replacement |
| FLNR536Y | No Replacement |
| FLNR548Y | No Replacement |
| FLNR624Y | No Replacement |
| FLNR636Y | No Replacement |
| FLNR648Y | No Replacement |
| FLNR936Y | No Replacement |
| FLNRX36Y | No Replacement |
| FLNRX48Y | No Replacement |
| FLNRZ36Y | No Replacement |
| FLNRZ48Y | No Replacement |

| | |
|---------|----------------|
| FLTN502 | No Replacement |
| FLTN504 | No Replacement |
| FLTN506 | No Replacement |
| FLTN508 | No Replacement |
| FLTN51A | No Replacement |
| FLTN524 | No Replacement |
| FLTN536 | No Replacement |
| FLTN548 | No Replacement |
| FLTN572 | No Replacement |
| FLTN596 | No Replacement |
| FLTN602 | No Replacement |
| FLTN604 | No Replacement |
| FLTN606 | No Replacement |
| FLTN608 | No Replacement |
| FLTN612 | No Replacement |
| FLTN61A | No Replacement |
| FLTN624 | No Replacement |
| FLTN636 | No Replacement |
| FLTN648 | No Replacement |
| FLTN672 | No Replacement |
| FLTN696 | No Replacement |
| FLTN902 | No Replacement |
| FLTN91A | No Replacement |
| FLTN936 | No Replacement |
| FLTN948 | No Replacement |
| FLTN972 | No Replacement |
| FLTN996 | No Replacement |
| FLTNX02 | No Replacement |
| FLTNX1A | No Replacement |
| FLTNX24 | No Replacement |
| FLTNX36 | No Replacement |
| FLTNX48 | No Replacement |
| FLTNX72 | No Replacement |
| FLTNX96 | No Replacement |
| FLTNZ02 | No Replacement |
| FLTNZ04 | No Replacement |
| FLTNZ08 | No Replacement |
| FLTNZ12 | No Replacement |
| FLTNZ1A | No Replacement |
| FLTNZ24 | No Replacement |
| FLTNZ36 | No Replacement |
| FLTNZ48 | No Replacement |
| FLTNZ72 | No Replacement |
| FLTNZ96 | No Replacement |
| FLWN502 | No Replacement |
| FLWN51A | No Replacement |
| FLWN524 | No Replacement |

| | |
|----------|----------------|
| FLWN536 | No Replacement |
| FLWN548 | No Replacement |
| FLWN572 | No Replacement |
| FLWN596 | No Replacement |
| FLWN602 | No Replacement |
| FLWN608 | No Replacement |
| FLWN612 | No Replacement |
| FLWN61A | No Replacement |
| FLWN624 | No Replacement |
| FLWN636 | No Replacement |
| FLWN648 | No Replacement |
| FLWN672 | No Replacement |
| FLWN696 | No Replacement |
| FLWN906Y | No Replacement |
| FLWN912Y | No Replacement |
| FLWN91A | No Replacement |
| FLWNX02 | No Replacement |
| FLWNX06Y | No Replacement |
| FLWNX12Y | No Replacement |
| FLWNX1A | No Replacement |
| FLWNX36 | No Replacement |
| FLWNX72 | No Replacement |
| FLWNX96 | No Replacement |
| FLWNZ02 | No Replacement |
| FLWNZ1A | No Replacement |
| FLWNZ36 | No Replacement |
| FLWNZ48 | No Replacement |
| FLWNZ72 | No Replacement |
| FLWNZ96 | No Replacement |
| FPQN502B | No Replacement |
| FPQN504B | No Replacement |
| FPQN506B | No Replacement |
| FPQN512B | No Replacement |
| FPQN51AB | No Replacement |
| FPQN524B | No Replacement |
| FPQN536B | No Replacement |
| FPQN548B | No Replacement |
| FPQN572B | No Replacement |
| FPQN596B | No Replacement |
| FPQN602B | No Replacement |
| FPQN604B | No Replacement |
| FPQN606B | No Replacement |
| FPQN608B | No Replacement |
| FPQN612B | No Replacement |
| FPQN61AB | No Replacement |
| FPQN624B | No Replacement |
| FPQN636B | No Replacement |

| | |
|----------|----------------|
| FPQN648B | No Replacement |
| FPQN672B | No Replacement |
| FPQN696B | No Replacement |
| FPQN902B | No Replacement |
| FPQN904B | No Replacement |
| FPQN906B | No Replacement |
| FPQN908B | No Replacement |
| FPQN936B | No Replacement |
| FPSN506 | No Replacement |
| FPSN508 | No Replacement |
| FPSN512 | No Replacement |
| FPSN524 | No Replacement |
| FPSN604 | No Replacement |
| FPSN606 | No Replacement |
| FPSN608 | No Replacement |
| FPSN612 | No Replacement |
| FPSN624 | No Replacement |
| FPTN506 | No Replacement |
| FPTN508 | No Replacement |
| FPTN512 | No Replacement |
| FPTN51A | No Replacement |
| FPTN524 | No Replacement |
| FPTN536 | No Replacement |
| FPTN548 | No Replacement |
| FPTN572 | No Replacement |
| FPTN596 | No Replacement |
| FPTN606 | No Replacement |
| FPTN608 | No Replacement |
| FPTN612 | No Replacement |
| FPTN61A | No Replacement |
| FPTN624 | No Replacement |
| FPTN636 | No Replacement |
| FPTN648 | No Replacement |
| FPTN672 | No Replacement |
| FPTN696 | No Replacement |
| FPTN906 | No Replacement |
| FPTN908 | No Replacement |
| FPTN912 | No Replacement |
| FPTN972 | No Replacement |
| FPUN502 | No Replacement |
| FPUN504 | No Replacement |
| FPUN506 | No Replacement |
| FPUN508 | No Replacement |
| FPUN512 | No Replacement |
| FPUN524 | No Replacement |
| FPUN602 | No Replacement |
| FPUN604 | No Replacement |

| | |
|----------|----------------|
| FPUN608 | No Replacement |
| FPUN612 | No Replacement |
| FPUN624 | No Replacement |
| FPUN902 | No Replacement |
| FPUN906 | No Replacement |
| FPUN908 | No Replacement |
| FPUN912 | No Replacement |
| FPUN924 | No Replacement |
| FQQNX02B | No Replacement |
| FQQNX04B | No Replacement |
| FQQNX06B | No Replacement |
| FQQNX08B | No Replacement |
| FQQNX12B | No Replacement |
| FQQNX1AB | No Replacement |
| FQQNX24B | No Replacement |
| FQQNX36B | No Replacement |
| FQQNX48B | No Replacement |
| FQQNX72B | No Replacement |
| FQQNX96B | No Replacement |
| FQQNZ02B | No Replacement |
| FQQNZ04B | No Replacement |
| FQQNZ06B | No Replacement |
| FQQNZ08B | No Replacement |
| FQQNZ12B | No Replacement |
| FQQNZ1AB | No Replacement |
| FQQNZ24B | No Replacement |
| FQQNZ36B | No Replacement |
| FQQNZ48B | No Replacement |
| FQQNZ72B | No Replacement |
| FQQNZ96B | No Replacement |
| FQSNX06 | No Replacement |
| FQSNX24 | No Replacement |
| FQSNZ04 | No Replacement |
| FQSNZ06 | No Replacement |
| FQSNZ08 | No Replacement |
| FQSNZ24 | No Replacement |
| FQTNX06 | No Replacement |
| FQTNX08 | No Replacement |
| FQTNX12 | No Replacement |
| FQTNX1A | No Replacement |
| FQTNX24 | No Replacement |
| FQTNX36 | No Replacement |
| FQTNX48 | No Replacement |
| FQTNX72 | No Replacement |
| FQTNX96 | No Replacement |
| FQTNZ06 | No Replacement |
| FQTNZ08 | No Replacement |

| | |
|-----------------|----------------|
| FQTNZ12 | No Replacement |
| FQTNZ1A | No Replacement |
| FQTNZ24 | No Replacement |
| FQTNZ36 | No Replacement |
| FQTNZ48 | No Replacement |
| FQTNZ72 | No Replacement |
| FQTNZ96 | No Replacement |
| FQUNX02 | No Replacement |
| FQUNX04 | No Replacement |
| FQUNX06 | No Replacement |
| FQUNX12 | No Replacement |
| FQUNX24 | No Replacement |
| FQUNZ02 | No Replacement |
| FQUNZ04 | No Replacement |
| FQUNZ06 | No Replacement |
| FQUNZ08 | No Replacement |
| FQUNZ12 | No Replacement |
| FQUNZ24 | No Replacement |
| PUC30100WH-AX/N | No Replacement |
| PUC3025WH-V/N | No Replacement |
| PUC3050WH-AX/N | No Replacement |
| PUC3050WH-V/N | No Replacement |
| PUL30100WH-AM/N | No Replacement |
| PUR30100WH-A/N | No Replacement |
| PUR30100WH-AM/N | No Replacement |
| PUZ30100WH-VD/N | No Replacement |
| PUZ3025WH-V1/N | No Replacement |
| PUZ3025WH-V3/N | No Replacement |
| PUZ3025WH-V5/N | No Replacement |
| PUZ3025WH-VD/N | No Replacement |
| PUZ3050WH-V2/N | No Replacement |
| PUZ3050WH-V3/N | No Replacement |
| PUZ3050WH-V4/N | No Replacement |
| PUZ3050WH-VD/N | No Replacement |
| PUC30100WH-AM/N | No Replacement |
| PUC5504BUY/S | No Replacement |
| PUC5504IG-EY/S | No Replacement |
| PUC5504IGY/S | No Replacement |
| PUC5504LBY/N | No Replacement |
| PUC5504YL-C/N | No Replacement |
| PUC5525BU-C/N | No Replacement |
| PUL5050WH-A/N | No Replacement |
| PUL5525BU-CD/N | No Replacement |
| PUL5525IG-PD/N | No Replacement |
| PUL5525WH-CD/N | No Replacement |
| PUP5504BU-UG/NY | No Replacement |
| PUP5C04BU-UTY/N | No Replacement |

| | |
|-----------------|----------------|
| PUP5C04BU-UY/N | No Replacement |
| PUP5C04GR-UQY/N | No Replacement |
| PUP5C04IG-UTY/N | No Replacement |
| PUP5C04VL-UQY/N | No Replacement |
| PUR5504IGY/S | No Replacement |
| PUR5525IG-UZ/N | No Replacement |
| PUR5525IG-UZY/N | No Replacement |
| PUR5C04GR-UQY/N | No Replacement |
| PUR5C04VL-UQY/N | No Replacement |
| PFL6004BU/N | No Replacement |
| PFZ6004BU-CEDN | No Replacement |
| PFZ6X04BU-C/N | No Replacement |
| PSO7004BL-KED/N | No Replacement |
| PUC6004GR-C/N | No Replacement |
| PUC6004OR-C/N | No Replacement |
| PUC6004WH-C/N | No Replacement |
| PUC6004YL-C/N | No Replacement |
| PUC6SD04DBU-CGN | No Replacement |
| PUC6SD04DWH-CGN | No Replacement |
| PUL6004GR-C/N | No Replacement |
| PUL6X04WH-D/N | No Replacement |
| PUO6C04BL-CET/N | No Replacement |
| PUP6004PK-UY/N | No Replacement |
| PUP6004RD-U/N | No Replacement |
| PUP6504BU-UT/N | No Replacement |
| PUR6C04GR-UY/N | No Replacement |
| PUR6C04RD-UY/N | No Replacement |
| PUR6C04VL-UQY/N | No Replacement |
| PUR6C04YL-UY/N | No Replacement |
| PUZ6004BL-CE/N | No Replacement |
| PUZ6004GR-CE/N | No Replacement |
| PUZ6004IG-CE/N | No Replacement |
| PUZ6004WH-BY/N | No Replacement |
| PUZ6004WH-CE/N | No Replacement |
| NUC6C04GP-CE/N | No Replacement |
| NUC6CR04AG-CE/N | No Replacement |
| NUC6CR04GP-CE/N | No Replacement |
| PFC6X04BU-C/N | No Replacement |
| PFL6X04WH-C/N | No Replacement |
| PFP6X04BL-UY/N | No Replacement |
| PFP6X04BU-UY/N | No Replacement |
| PFP6X04IG-UY/N | No Replacement |
| PFZ6X04WH-C/N | No Replacement |
| PSL6X04AWH-CEGN | No Replacement |
| PSL6X04WH-CEG/N | No Replacement |
| PSL6XSD04WHCEDN | No Replacement |
| PSL7004DG-KD1/N | No Replacement |

| | |
|-----------------|----------------|
| PSMD7004GG-KEDN | No Replacement |
| PSMD7004WG-NEDN | No Replacement |
| PSW7004DG-CED/N | No Replacement |
| PSZ7004BU-CED/N | No Replacement |
| PUFL26X04WH-D/N | No Replacement |
| PUFL6X04GR-CEDN | No Replacement |
| PUFL6X04YL-CEDN | No Replacement |
| PUL6A08BU-CEDN | No Replacement |
| PUL6A08WH-CEDN | No Replacement |
| PUL6AM04BR-CEGN | No Replacement |
| PUL6AM04PK-CEGN | No Replacement |
| PUL6ASD04BR-EGN | No Replacement |
| PUL6ASD08BUCEDN | No Replacement |
| PUL6ASD08WHCEDN | No Replacement |
| PUP6A04BU-UX/N | No Replacement |
| PUP6A04GR-UQ/N | No Replacement |
| PUP6AM04BU-UTN | No Replacement |
| PUP6AM04WH-UTN | No Replacement |
| PUR66X4WH-U/N | No Replacement |
| PUR6A04BU-UG/N | No Replacement |
| PUR6A04BU-UQ/N | No Replacement |
| PUR6A04WH-UG/N | No Replacement |
| PUR6AM04WH-CG-S | PUR6AV04WH-G-S |
| PUZ6A04WH-EM/N | No Replacement |
| PUZ6X04BU-E/N | No Replacement |
| PUZ6X04WH-E/N | No Replacement |
| PTGL05A-BTJJ/N | No Replacement |
| FLDA912SDT/BL | No Replacement |
| FLDA912SDT/BR | No Replacement |
| FLDA912SDT/BU | No Replacement |
| FLDA912SDT/IG | No Replacement |
| FLDA912SDT/PK | No Replacement |
| FLDA912SDT/VL | No Replacement |
| FLDA912SDT/WH | No Replacement |
| FLDA912SDT/YL | No Replacement |
| FLDL91A/N | No Replacement |
| FLDL924Y/NS | No Replacement |
| FLDL972Y | No Replacement |
| FLDLX1AY/N | No Replacement |
| FLDLX72Y | No Replacement |
| FLDR596Y/N | No Replacement |
| FLDR91A/N | No Replacement |
| FLDR996Y/N | No Replacement |
| FLDRZ24Y/N | No Replacement |
| FLDZ906Y/N | No Replacement |
| FLDZX06Y/N | No Replacement |
| FLIR902Y-BU/N | No Replacement |

| | |
|---------------|----------------|
| FLIRX02Y-BU/N | No Replacement |
| FLIZ904Y/N | No Replacement |
| FLIZX02Y/N | No Replacement |
| FLIZX04Y/N | No Replacement |
| FLNR996Y/N | No Replacement |
| FLQN912E/N | No Replacement |
| FLQN924E/N | No Replacement |
| FLQN948E/N | No Replacement |
| FLQN996E/N | No Replacement |
| FLSNX06Y/N | No Replacement |
| FLTNA06/SD | No Replacement |
| FLTNA12/SD | No Replacement |
| FLTNA24/SD | No Replacement |
| FLTNA48/SD | No Replacement |
| FLTN506Y/N | No Replacement |
| FLTN512Y/N | No Replacement |
| FLTN612Y/N | No Replacement |
| FLTN906Y/N | No Replacement |
| FLTN9120Y/N | No Replacement |
| FLTN912Y/N | No Replacement |
| FLTN924Y/N | No Replacement |
| FLTNA06/SD | No Replacement |
| FLTNA12/SD | No Replacement |
| FLTNA24/SD | No Replacement |
| FLTNA48/SD | No Replacement |
| FLTNX06Y/N | No Replacement |
| FLWL924/N | No Replacement |
| FLWLZ24/N | No Replacement |
| FLWN504Y/N | No Replacement |
| FLWN506Y/N | No Replacement |
| FLWN508Y/N | No Replacement |
| FLWN512Y/N | No Replacement |
| FLWN524Y/N | No Replacement |
| FLWN606Y/N | No Replacement |
| FLWN612Y/N | No Replacement |
| FLWN904Y/N | No Replacement |
| FLWN906Y/N | No Replacement |
| FLWN908Y/N | No Replacement |
| FLWN912Y/N | No Replacement |
| FLWN924Y/N | No Replacement |
| FLWN936Y/N | No Replacement |
| FLWN948/CAMR | No Replacement |
| FLWN948Y/N | No Replacement |
| FLWN960Y/N | No Replacement |
| FLWNX04Y/N | No Replacement |
| FLWNX06Y/N | No Replacement |
| FLWNX08Y/N | No Replacement |
| FLWNX12Y/N | No Replacement |
| FLWNX24Y/N | No Replacement |
| FLWNZ06Y/N | No Replacement |
| FLWNZ12Y/N | No Replacement |

| | |
|---------------|----------------|
| FLWNZ24Y/N | No Replacement |
| FOCPZ12Y/LPF | No Replacement |
| FOCRX06Y/LL | No Replacement |
| FODLX08Y/N | No Replacement |
| FODLX1A/N | No Replacement |
| FODLX48Y/N | No Replacement |
| FODLX72Y/N | No Replacement |
| FODPX02Y/GN | No Replacement |
| FODPX06Y/LL | No Replacement |
| FODPX12Y/OR | No Replacement |
| FODPX12Y/YL | No Replacement |
| FODPX1A/N | No Replacement |
| FSPRK60-Z36/N | No Replacement |
| FODPX96Y/N | No Replacement |
| FODPZ12K/N | No Replacement |
| FODPZ12Y/N | No Replacement |
| FODRX02Y/N | No Replacement |
| FODRX1AY/N | No Replacement |
| FODRX72Y/N | No Replacement |
| FODRX96Y/N | No Replacement |
| FODRZ24Y/N | No Replacement |
| FOGLZ12/N | No Replacement |
| FOGPX12Y/N | No Replacement |
| FOGPZ12Y/N | No Replacement |
| FOKLX06/N | No Replacement |
| FOKLZ12/N | No Replacement |
| FOKP912/N | No Replacement |
| FOKPX12/N | No Replacement |
| FOMRZ24Y/N | No Replacement |
| FONPX96Y/N | No Replacement |
| FONRX72Y/N | No Replacement |
| FOPDX06/N | No Replacement |
| FOPLX24Y/N | No Replacement |
| FOPLZ08/N | No Replacement |
| FOPLZ12/N | No Replacement |
| FOPLZ48/N | No Replacement |
| FOPPX06Y/N | No Replacement |
| FOPPX12Y/WHT | No Replacement |
| FOPPZ12Y/N | No Replacement |
| FOWNX24/N | No Replacement |
| FPCL606/N | No Replacement |
| FPCL902/N | No Replacement |
| FPCL904/N | No Replacement |
| FPCL908/N | No Replacement |
| FPCL912/N | No Replacement |
| FPCL924/N | No Replacement |
| FPCLB04/N | No Replacement |

| | |
|----------------|----------------|
| FPCLB12/N | No Replacement |
| FPCLB24/N | No Replacement |
| FPCLB48/N | No Replacement |
| FPDL906/N | No Replacement |
| FPML972/N | No Replacement |
| FPNL948/FIBR | No Replacement |
| FPNLB48/N | No Replacement |
| FPNLB948/N | No Replacement |
| FPNLJ24-X12/N | No Replacement |
| FPNLJ48-X24/N | No Replacement |
| FPON512/N | No Replacement |
| FPON906/N | No Replacement |
| FPON912/N | No Replacement |
| FPON91A/N | No Replacement |
| FPON924/N | No Replacement |
| FPON936Y/N | No Replacement |
| FPON948/N | No Replacement |
| FPON972/N | No Replacement |
| FPONX48/N | No Replacement |
| FPQN906-SADJ/N | No Replacement |
| FPQN924B/N | No Replacement |
| FPQN948B/N | No Replacement |
| FPRNX08/N | No Replacement |
| FPSN504/N | No Replacement |
| FPSN508/N | No Replacement |
| FPSN512/N | No Replacement |
| FPSN604/N | No Replacement |
| FPSN606/N | No Replacement |
| FPSN908/N | No Replacement |
| FPSN912/N | No Replacement |
| FPSN912/NZDSF | No Replacement |
| FPSN916/N | No Replacement |
| FPSN924/N | No Replacement |
| FPSN924/NZDSF | No Replacement |
| FPSNX04/N | No Replacement |
| FPSNX06/N | No Replacement |
| FPSNX08/N | No Replacement |
| FPSNX12/N | No Replacement |
| FPSNZ06/N | No Replacement |
| FPSNZ12/N | No Replacement |
| FPTND72/NZDSF | No Replacement |
| FPWN948/NZDSF | No Replacement |
| FQCLX02/N | No Replacement |
| FQCLX16/NS | No Replacement |
| FQCLZ02/N | No Replacement |
| FQDLX06/N | No Replacement |
| FQDLX08/N | No Replacement |

| | |
|----------------|----------------|
| FQDLX12/N | No Replacement |
| FQDLZ06/N | No Replacement |
| FQDLZ24/N | No Replacement |
| FQILX02/N | No Replacement |
| FQNLX12/N | No Replacement |
| FQNLX1A/N | No Replacement |
| FQNLX24/N | No Replacement |
| FQRNX02/N | No Replacement |
| FQTNZ12/N | No Replacement |
| FSCR912Y/N | No Replacement |
| FSDL91A/N | No Replacement |
| FSDL948/N | No Replacement |
| FSDL948Y/N | No Replacement |
| FSDL972/N | No Replacement |
| FSDL972Y/N | No Replacement |
| FSDP602Y/N | No Replacement |
| FSDP906Y/N | No Replacement |
| FSDP912A-GR/N | No Replacement |
| FSDP912Y/N | No Replacement |
| FSDP91A/N | No Replacement |
| FSDP924Y/N | No Replacement |
| FSDR906Y ACP | No Replacement |
| FSDR912Y ACP | No Replacement |
| FSDR91A/N | No Replacement |
| FSDR924Y ACP | No Replacement |
| FSDR948Y ACP | No Replacement |
| FSDR972Y/N | No Replacement |
| FSDRJ48-X24/N | No Replacement |
| FSIR502-AQ/N | No Replacement |
| FSKL924/N | No Replacement |
| FSKR606Y/N ACP | No Replacement |
| FSKR612Y/N ACP | No Replacement |
| FSKR912Y/N ACP | No Replacement |
| FSKRH24-126/N | No Replacement |
| FSL912/N | No Replacement |
| FSNL972Y/N | No Replacement |
| FSNP912Y/N | No Replacement |
| FSNPJ30-X24/N | No Replacement |
| FSNR924Y/LL | No Replacement |
| FSOP548Y/N | No Replacement |
| FSOP91AY/N | No Replacement |
| FSOP996Y/N | No Replacement |
| FSOPA24/RCLT | No Replacement |
| FSOPA72/RCLT | No Replacement |
| FSORA24/RCLT | No Replacement |
| FSPD912-YL | No Replacement |
| FSPL912Y/N | No Replacement |

| | |
|-----------------|----------------|
| FSPP906Y/WHT | No Replacement |
| FSPPJ12-X06RD/N | No Replacement |
| FSPR918Y/N | No Replacement |
| FSPRH48-612/N | No Replacement |
| FSPRH48-624Y/N | No Replacement |
| FSPRK12-Z06/N | No Replacement |
| FSPRK36-Z24/N | No Replacement |
| FSTN906/2M | No Replacement |
| FSTN906/2M ACP | No Replacement |
| FSTN906/RD | No Replacement |
| FSTN912/2M | No Replacement |
| FSTN912/2M ACP | No Replacement |
| FSTN912/N | No Replacement |
| FSTN912/RD | No Replacement |
| FSTN924/N | No Replacement |
| FSTN924/RD | No Replacement |
| FSTN924D/PCP | No Replacement |
| FSTN948/2M | No Replacement |
| FSTN948/2M ACP | No Replacement |
| FSTN948/RD | No Replacement |
| FSTN94A/RCLT | No Replacement |
| FSTN96A/RCLT | No Replacement |
| FSTN96A/RILT | No Replacement |
| FSTN972/2M | No Replacement |
| FSTN972/2M ACP | No Replacement |
| FSTN996/RD | No Replacement |
| FSTNA5A/RILT | No Replacement |
| FSTNJ12-X06/N | No Replacement |
| FSTNJ72-X24/N | No Replacement |
| FSWN504Y/N | No Replacement |
| FSWN912Y/N | No Replacement |
| FSWN91A/N | No Replacement |
| FSWN924/6T | No Replacement |
| FSWN936Y/N | No Replacement |
| FSWNA1A/RCLT | No Replacement |
| FSWNA3A/RCLT | No Replacement |
| FSWNA96/RCLT | No Replacement |
| FSXN906M8/N | No Replacement |
| FSXN912M/N | No Replacement |
| FSXN912M150/N | No Replacement |
| FSXN924H5/N | No Replacement |
| FSXN924L/N | No Replacement |
| FSXN924L150/N | No Replacement |
| FSXN924M1/N | No Replacement |
| FSXN924M120/N | No Replacement |
| FSXN924M150/N | No Replacement |
| FSXN924M3/N | No Replacement |

| | |
|--------------|----------------|
| FSXN924M50/N | No Replacement |
| FSXN924M8/N | No Replacement |
| FSXN936/N | No Replacement |
| FSXN936M3/N | No Replacement |
| FSXN948H3/N | No Replacement |
| FSXN948L/N | No Replacement |
| FSXN948M/N | No Replacement |
| FSYN906/N | No Replacement |
| FSYN912/N | No Replacement |
| FSYN924/N | No Replacement |
| FSYN948Y/N | No Replacement |