

Product Discontinuation



PD_204_18

| | |
|-----------------------|------------|
| ■ Last Order Date: | 2019-05-30 |
| ■ Last Delivery Date: | 2019-11-30 |

Reason: Adjustment Portfolio

| DISCONTINUED | | | | NEW (REPLACEMENT) | | | |
|--------------|-------------|------------------|-----------|-------------------|-------------|------------------|-----------|
| Sales name | SP number | OPN | Package | Sales name | SP number | OPN | Package |
| TD142N12KOF | SP000089598 | TD142N12KOFHPSA1 | BG-PB34-1 | TD142N16KOF | SP000091527 | TD142N16KOFHPSA1 | BG-PB34-1 |
| TT61N12KOF | SP000096672 | TT61N12KOFHPSA1 | BG-PB20-1 | TT61N14KOF | SP000096674 | TT61N14KOFHPSA1 | BG-PB20-1 |
| TT162N12KOF | SP000096733 | TT162N12KOFHPSA1 | BG-PB34-1 | TT162N14KOF | SP000096734 | TT162N14KOFHPSA1 | BG-PB34-1 |

If you have any questions, please do not hesitate to contact your local sales office.

Disclaimer: The supply of this product will stop after the date of last delivery as outlined herein. Final orders can only be accepted on or before the last order date and are subject to the availability. Early ordering is strongly recommended!