

	LFB2H2G45SG7A134	
	Hersteller-Teilenummer:	LFB2H2G45SG7A134
Hersteller / Marke:	MURATA	
Teil der Beschreibung:	LFB2H2G45SG7A134 MURATA	
RoHs Status:		
Lagerzustand:	New original, 8908 pcs Stock Available.	
Liefern von:	Hong Kong	
Versandweg:	DHL/Fedex/TNT/UPS/EMS	
Image may be representation. See specs for product details.		

Spezifikationen

Teilenummer	LFB2H2G45SG7A134
Hersteller	MURATA
Beschreibung	LFB2H2G45SG7A134 MURATA
Kategorie	Integrierte Schaltungen (ICs) > Specialized Hot ICs
Teilstatus	8908 pcs Stock
Serie	-
RoHs Status	Lead free / RoHS Compliant
Bedingung	New Original Stock
Garantie	100% Perfect Functions
Vorlaufzeit	2-3days after payment.
Zahlung	PayPal / Telegraphic Transfer / Western Union
Versand per	DHL / Fedex / UPS
Hafen	HongKong
Anfrage-E-Mail	Info@Y-IC.com

LFB2H2G45SG7A134 ist neu im Original, Suche LFB2H2G45SG7A134 Datenblätter, PDF, Inventar bei Y-IC.com Online, Bestellen Sie LFB2H2G45SG7A134 mit Garantie und Vertrauen. Anfrage LFB2H2G45SG7A134: Info@Y-IC.com

Sie können auch interessiert sein:

 LFB2H2G45CG1C026 MURATA LFB2H2G45CG1C026 MURATA	 LFB2H2G45SG7A158 Murata Electronics 2450.0 MHZ MULTI LAYER CHIP	 LFB2H2G45BB1A221 MURATA LFB2H2G45BB1A221 MURATA	 LFB2H2G45SG7A204 MuRata LFB2H2G45SG7A204 MuRata
 LFB2H2G45BB1A243 murata LFB2H2G45BB1A243 murata	 LFB2H2G44BB5B896 MURATA LFB2H2G44BB5B896 MURATA	 LFB2H2G45SG7A159 MURATA LFB2H2G45SG7A159 MURATA	 LFB2H2G45SG7A135 Original LFB2H2G45SG7A135 Original

heiße Teile

Mehr

- | | | | | |
|--------------------|--------------------|--------------------|--------------------|--------------------|
| ⚙ LFB212G49SG8B830 | ➔ LFB212G60BB1D295 | ➔ LFB213G50CF3D087 | D LFB213G60SG8B831 | ➔ LFB213G82SG8A199 |
| ⊖ LFB215G37BA1A233 | ⚙ LFB215G37SG8A180 | D LFB215G37SG8A185 | ➔ LFB215G42SG8A300 | ➔ LFB215G42SGKD065 |
| ⚙ LFB215G51SG8A132 | ⊖ LFB215G51SG8A154 | ⚙ LFB215G78SG8A170 | ➔ LFB215G80SG8A115 | ➔ LFB21914MDZ2D326 |
| D LFB21914MDZ3D384 | ⚙ LFB2H1G90SG6B812 | ⊖ LFB2H1G90SG7C257 | ⚙ LFB2H1G91SG7A198 | ➔ LFB2H2G34BB1C160 |
| ➔ LFB2H2G44BB5B896 | ➔ LFB2H2G45BB1A221 | ⚙ LFB2H2G45BB1A243 | ⊖ LFB2H2G45CC1D005 | ➔ LFB2H2G45CG1C026 |
| ➔ LFB2H2G45SG7A135 | ➔ LFB2H2G45SG7A158 | D LFB2H2G45SG7A159 | ⚙ LFB2H2G45SG7A204 | ⊖ LFB2H2G45SG7B734 |
| ⚙ LFB2H2G45SG7B793 | D LFB2H2G45SG7C093 | ➔ LFB2H2G45SG7C220 | ➔ LFB2H2G45SGFB914 | ➔ LFB2H2G45SGFC217 |
| ⊖ LFB2H2G45SGFD083 | ⚙ LFB2H2G59SG7B858 | ➔ LFB2H2G60BB1B973 | ➔ LFB2H2G60BB1C106 | ➔ LFB2H3G50BB2C146 |
| ⚙ LFB2H5G78SG7A175 | ⊖ LFB311G44SG1A558 | ⚙ LFB311G50SL1A500 | D LFB311G89SP1A542 | ➔ LFB311G90SG1-799 |
| ➔ LFB311G90SG2-797 | ⚙ LFB311G90SP1-798 | ⊖ LFB311G90SP1A519 | ⚙ LFB311G90SP1A637 | ➔ LFB311G95SG3A564 |

Contact us: Info@Y-IC.com

HINZUFÜGEN: Einheit A5-B5 Nr.509, 5 / F Sing Win Fabrikgebäude, 15-17 Shing Yip St, Kwun Tong, Kowloon, HongKong.
Copyright © 2019 YIC International Co., Limited